



PB94-186343

Publication No. FHWA-RD-93-113

July 1994

---

# Testing of Small and Large Sign Support Systems FOIL Test Numbers: 92F024 and 92F025



U.S. Department of Transportation  
**Federal Highway Administration**

Research and Development  
Turner-Fairbank Highway Research Center  
6300 Georgetown Pike  
McLean, Virginia 22101-2296

REPRODUCED BY  
U.S. Department of Commerce  
National Technical Information Service  
Springfield, Virginia 22161



#### NOTICE

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no liability for its contents or use thereof. This report does not constitute a standard, specification, or regulation.

The United States Government does not endorse products or manufacturers. Trade and manufacturers' names appear in this report only because they are considered essential to the object of the document.



1. Report No. FHWA-RD-93-113		2.  PB94-186343		3. Rec Tech	
4. Title and Subtitle TESTING OF SMALL AND LARGE SIGN SUPPORT SYSTEMS FOIL TEST NUMBERS: 92F024 AND 92F025				5. Report Date	
				6. Performing Organization Code	
7. Author(s) Christopher M. Brown				8. Performing Organization Report No.	
9. Performing Organization Name and Address Advanced Technology & Research Corp. 14900 Sweitzer Lane Laurel, MD 20707				10. Work Unit No. (TRAIS) 3A5f3142	
				11. Contract or Grant No. DTFH61-91-Z-00002	
12. Sponsoring Agency Name and Address Office of Safety and Traffic Operations R&D Federal Highway Administration 6300 Georgetown Pike McLean, VA 22101-2296				13. Type of Report and Period Covered Test Report, August 1992	
				14. Sponsoring Agency Code	
15. Supplementary Notes Contracting Officer's Technical Representative (COTR) - Richard King, HSR-20					
16. Abstract <p>This test report contains the results of two crash tests performed at the Federal Outdoor Impact Laboratory (FOIL) in McLean, Virginia. The tests were performed on a small sign support system at 20 mi/h (8.9 m/s), test 92F024, and 60 mi/h (26.8 m/s), test 92F025. The vehicle used for these tests were a 1984 and a 1985 Honda Civic three-door hatchback with manual transmission. The purpose of the tests was to evaluate the low- and high-speed safety performance of a dual legged steel 2 lb/ft (2.98 kg/m) braced sign support. The performance evaluation was based on the latest requirements for breakaway supports as specified in Volume 54, Number 3 of the Federal Register dated January 5, 1989. These criteria specify, in part, that the occupant change in velocity must be 16 ft/s (4.9 m/s) or less, that the significant test article stub height remaining after impact be no more than 4 in (101.6 mm), and that there can be no occupant compartment intrusion. The test results indicate that the dual legged 2 lb/ft (2.98 kg/m) braced sign support system meets all of the applicable criteria for the low- and high-speed test in weak soil specified by the FHWA.</p>					
17. Key Words Acceleration, occupant impact velocity, weak soil, u-channel, sign, vehicle, FOIL.			18. Distribution Statement No restrictions. This document is available to the public through the National Technical Information Service Springfield, Virginia 22161		
19. Security Classif. (of this report) Unclassified		20. Security Classif. (of this page) Unclassified		21. No. of Pages 32	22. Price

# SI\* (MODERN METRIC) CONVERSION FACTORS

## APPROXIMATE CONVERSIONS TO SI UNITS

## APPROXIMATE CONVERSIONS FROM SI UNITS

Symbol	When You Know	Multiply By	To Find	Symbol	When You Know	Multiply By	To Find	Symbol
<b>LENGTH</b>								
in	inches	25.4	millimeters	mm	millimeters	0.039	inches	in
ft	feet	0.305	meters	m	meters	3.28	feet	ft
yd	yards	0.914	meters	m	meters	1.09	yards	yd
mi	miles	1.61	kilometers	km	kilometers	0.621	miles	mi
<b>AREA</b>								
in <sup>2</sup>	square inches	645.2	square millimeters	mm <sup>2</sup>	square millimeters	0.0016	square inches	in <sup>2</sup>
ft <sup>2</sup>	square feet	0.093	square meters	m <sup>2</sup>	square meters	10.764	square feet	ft <sup>2</sup>
yd <sup>2</sup>	square yards	0.836	square meters	m <sup>2</sup>	square meters	1.195	square yards	ac
ac	acres	0.405	hectares	ha	hectares	2.47	acres	mi <sup>2</sup>
mi <sup>2</sup>	square miles	2.59	square kilometers	km <sup>2</sup>	square kilometers	0.386	square miles	
<b>VOLUME</b>								
fl oz	fluid ounces	29.57	milliliters	ml	milliliters	0.034	fluid ounces	fl oz
gal	gallons	3.785	liters	l	liters	0.264	gallons	gal
ft <sup>3</sup>	cubic feet	0.028	cubic meters	m <sup>3</sup>	cubic meters	35.71	cubic feet	ft <sup>3</sup>
yd <sup>3</sup>	cubic yards	0.765	cubic meters	m <sup>3</sup>	cubic meters	1.307	cubic yards	yd <sup>3</sup>
<b>MASS</b>								
oz	ounces	28.35	grams	g	grams	0.035	ounces	oz
lb	pounds	0.454	kilograms	kg	kilograms	2.202	pounds	lb
T	short tons (2000 lb)	0.907	megagrams	Mg	megagrams	1.103	short tons (2000 lb)	T
<b>TEMPERATURE (exact)</b>								
°F	Fahrenheit temperature	5(F-32)/9 or (F-32)/1.8	Celsius temperature	°C	Celsius temperature	1.8C + 32	Fahrenheit temperature	°F
<b>ILLUMINATION</b>								
fc	foot-candles	10.76	lux	lx	lux	0.0929	foot-candles	fc
fl	foot-Lamberts	3.426	candela/m <sup>2</sup>	cd/m <sup>2</sup>	candela/m <sup>2</sup>	0.2919	foot-Lamberts	fl
<b>FORCE and PRESSURE or STRESS</b>								
lbf	poundforce	4.45	newtons	N	newtons	0.225	poundforce	lbf
psi	poundforce per square inch	6.89	kilopascals	kPa	kilopascals	0.145	poundforce per square inch	psi

NOTE: Volumes greater than 1000 l shall be shown in m<sup>3</sup>.

\* SI is the symbol for the International System of Units. Appropriate rounding should be made to comply with Section 4 of ASTM E380.

Table of Contents.

1. SCOPE . . . . .	1
2. TEST MATRIX . . . . .	1
3. VEHICLE . . . . .	1
4. SIGN SUPPORT . . . . .	1
5. TEST RESULTS - 20 MI/H (8.9 M/S), TEST 92F024 . . . . .	2
6. TEST RESULTS - 60 MI/H (26.8 M/S), TEST 92F025 . . . . .	3
7. CONCLUSION . . . . .	4
8. REFERENCES . . . . .	28

## List of Figures.

<u>Figure No.</u>	<u>Page</u>
1. Sketch of small sign support . . . . .	5
2. Sketch of small sign support, attachment detail . . . . .	6
3. Test photographs during impact, test 92F024 . . . . .	7
4. Summary of test 92F024 . . . . .	8
5. Acceleration versus time, X-axis, test 92F024 . . . . .	9
6. Velocity versus time, X-axis, test 92F024 . . . . .	10
7. Force versus displacement, X-axis, test 92F024 . . . . .	11
8. Occupant velocity and relative displacement versus time, X-axis, test 92F024 . . . . .	12
9. Pretest photographs of test 92F024 . . . . .	13
10. Post-test photographs of test 92F024 . . . . .	15
11. Test photographs during impact, test 92F025 . . . . .	17
12. Summary of test 92F025 . . . . .	18
13. Acceleration versus time, X-axis, test 92F025 . . . . .	19
14. Velocity versus time, X-axis, test 92F025 . . . . .	20
15. Force versus displacement, X-axis, test 92F025 . . . . .	21
16. Occupant velocity and relative displacement versus time, X-axis, test 92F025 . . . . .	22
17. Pretest photographs of test 92F025 . . . . .	23
18. Post-test photographs of test 92F025 . . . . .	25
19. Sketch of vehicle crush, test 92F025 . . . . .	27

## List of Tables.

<u>Table No.</u>	
1. Test matrix . . . . .	1

## 1. SCOPE

This test report contains the results of two crash tests performed at the Federal Outdoor Impact Laboratory (FOIL) in McLean, Virginia. The tests were performed on a small sign support system, one at 20 mi/h (8.9 m/s), test 92F024, and one at 60 mi/h (26.8 m/s), test 92F025. The vehicles used for these tests were Honda Civic two door hatchbacks. The purpose of these tests was to evaluate the low- and high-speed safety performance of a dual legged braced 2 lb/ft (2.98 kg/m) u-channel sign support system in weak soil. The performance evaluation was based on the latest requirements for breakaway supports as specified in Volume 54, Number 3 of the Federal Register dated January 5, 1989. These criteria specify, in part, that the occupant change in velocity must be 16 ft/s (4.9 m/s) or less, that the significant test article stub height remaining after impact be no more than 4 in (101.6 mm), and that there can be no occupant compartment intrusion.

## 2. TEST MATRIX

Two tests were performed on a small sign support system. The test speeds for the tests were 20 mi/h (8.9 m/s) and 60 mi/h (26.8 m/s). The sign was buried in NCHRP Report Number 230, S-2 weak soil<sup>(1)</sup>. A summary of the test conditions is presented in table 1.

Test Number	Test Date	Test Vehicle	Test Weight (lb)	Test Speed (mi/h)	Test Article Description	Impact Location
92F024	8-19-92	'85 Honda Civic	1850	20	2 leg 2 lb/ft u-channel braced	center
92F025	8-25-92	'84 Honda Civic	1850	60	2 leg 2 lb/ft u-channel braced	center

## 3. VEHICLE

The test vehicles were a 1985 and a 1984 Honda Civic two door hatchback with manual transmissions. Prior to the tests, the vehicles' fluids were drained and their inertial measurements measured. The vehicles were stripped of certain components which made space for the installation of test equipment. The vehicles were ballasted with data acquisitions systems, transducers, a brake system and weight plates (if necessary) to bring their inertial weights to approximately 1850 lb (839 kg). The actual weight of the test vehicles was 1850 lb (839 kg). After ballasting, the vehicles' inertial properties were remeasured.

## 4. SIGN SUPPORT

The sign support system used in these tests consisted of an 8-ft wide by 6-ft (2.4-m by 1.8-m) high aluminum sign panel mounted to two 2 lb/ft (2.98 kg/m) u-channel posts. The two posts were installed 3.5 ft (1.1 m) apart. The posts were spliced to two 6-ft 11-in (2.1-m) stubs which were

installed 3.5 ft (1.1 m) deep in NCHRP, S-2 weak soil (sand). The splice was a 2-ft (0.6-m) overlap splice which started 18 in (457.2 mm) above ground. The splice was configured with the sign posts behind the splice stubs. The overlap splice was fastened using two 3/8-in-(9.5-mm) diameter aluminum bolts. The bolts were 19 in (482.6 mm) and 39 in (990.6 mm) above ground level. The two posts were supported in the rear by an angled wind brace. The wind brace was made from 2 lb/ft (2.98 kg/m) u-channel and was attached to the two sign posts 10 ft (3.1 m) above ground. The other end of the brace was attached to a 3-ft 10-in (1.2-m) stub which was embedded 3.5 ft (1.1 m) in the weak soil. The rear brace stubs were installed 5.5 ft (1.7 m) behind the two vertical sign posts. The two brace stubs were offset 6 in (152.4 mm) on center with the two vertical sign posts. All of the brace attachments, four in total, were made using one aluminum bolt. Figures 1 and 2 are drawings of the sign support system details.

## 5. TEST RESULTS - 20 MI/H (8.9 M/S), TEST 92F024

The test vehicle was accelerated to 21.5 mi/h (31.6 ft/s (9.6 m/s)) prior to impacting the sign support. The centerline of the test vehicle was aligned with the mid point between the two sign posts.

The bumper made contact with both sign posts on the lower splice bolt, 19 in (482.6 mm) above ground. The sign posts began to push through the weak soil and bow away from the vehicle. The u-channel posts were pushed through the sand 12 in (304.8 mm). The four aluminum splice bolts broke approximately 0.04 s after initial contact. The bumper did not crush significantly during the impact event. The breakaway force was low enough not to cause severe damage to the front end of the vehicle. The upper u-posts began to rotate away from the vehicle while the vehicle continued to flatten the two 3-ft 5-in (1.0-m) splice stubs. The vehicle flattened the two stubs and proceeded forward and made contact with the braces. The vehicle detached the braces from their support stubs while the sign panel fell on the roof of the test vehicle. While the vehicle was rolling over the front stubs, the front stubs began to recoil from the bent position and push upwards on the rear of the vehicle causing the vehicle to pitch. The induced pitch caused concern for higher impact speeds. The pitching motion could cause the vehicle to roll during higher impact speed collisions. After the vehicle exited the sign system the brakes were applied and the vehicle came to rest.

Damage to the vehicle consisted of minor damage to the bumper and a dent approximately 0.5 in (12.7 mm) deep just above the left B-pillar. The two parking lights just below the bumper were shattered. Since no considerable damage was inflicted on the front end of the vehicle no crush measurements were recorded or documented in this report. The damage to the roof was light and just above the B-pillar. No damage was inflicted on the windshield. None of the sign components impaled the occupant compartment.

Damage to the sign support was mainly to the front splice stubs. The stubs were bent and contorted and not reusable. All of the aluminum hardware used to assemble the sign support was destroyed. The splice bolts failed in tension while the brace bolts sheared. The remainder of the u-channel, the braces, the rear brace stubs (in the ground) and the u-channel attached to the sign panel was in usable condition after the test. The braces were launched downrange 30 ft (9.2 m). This is a possible hazard for other traffic and pedestrians.

The occupant impact velocity using the 2-ft (0.6-m) flail space model outlined in NCHRP Report Number 230, was determined to be 11.5 ft/s (3.5 m/s).

The occupant impact velocity was reached 0.255 s into the crash event. The ridedown acceleration was 1.4 g's. The peak force (300 Hz data) for the impact event was 6.3 g's (11.6 kips (51 kN)). Because the sign support-vehicle contact was prolonged the vehicle change in velocity was calculated to be 14.6 ft/s (4.4 m/s).

Photographs during the impact event are presented in figure 3. A summary of the impact conditions and the test results is presented in figure 4. Figures 5 through 8 are plots of data collected during the test. Pre- and post-test photographs of the vehicle and sign support system are presented in figures 9 through 12. Because no residual crush was recorded a sketch depicting the crush was omitted from this report.

## 6. TEST RESULTS - 60 MI/H (26.8 M/S), TEST 92F025

The test vehicle was accelerated to 60.4 mi/h (88.6 ft/s (27.0 m/s)) prior to impacting the sign support. The centerline of the test vehicle was aligned with the mid point between the two sign posts.

The bumper made contact with both sign posts on the lower splice bolt, 19 in (482.6 mm) above ground. The sign posts began to push through the weak soil and bow away from the vehicle. The u-channel posts were pushed through the sand 12 in (304.8 mm). The four aluminum splice bolts broke approximately 0.014 s after initial contact. The upper u-posts began to rotate away from the vehicle while the vehicle continued to flatten the two 3-ft 5-in (1.0-m) splice stubs. The vehicle flattened the two stubs and proceeded forward and made contact with the braces. The vehicle detached and launched the braces from their support stubs 0.06 s into the crash event. While the vehicle was rolling over the front stubs, they began to recoil from the bent position, however the vehicle was traveling too fast for the rebounding u-channel to impart any pitch motion on the vehicle. After the vehicle exited the sign system the brakes were applied and the vehicle came to rest with help from the FOIL catch fence.

Damage to the vehicle consisted of damage to the bumper and a dent on either side of the hood. The two parking lights just below the bumper were shattered along with both headlights and plastic cosmetic bumper elements. The u-channel penetrated the bumper on the outside edge of each bumper support. The penetration was deep enough to cause damage to minor frame members behind the headlights. No damage was inflicted on the roof or windshield. None of the sign components impaled the occupant compartment.

Damage to the sign support was mainly to the front splice stubs. The stubs were bent and contorted and not reusable. All of the aluminum hardware used to assemble the sign support was destroyed. The splice bolts failed in tension while the brace bolts sheared. The remainder of the u-channel, the braces, the rear brace stubs (in the ground) and the u-channel attached to the sign panel was in usable condition after the test. The braces were launched downrange 110 ft (33.5 m) and 300 ft (91.5 m). This is a possible hazard for other traffic and pedestrians.

The occupant impact velocity using the 2-ft (0.6-m) flail space model outlined in NCHRP Report Number 230, was determined to be 8.4 ft/s (2.6 m/s). The occupant impact velocity was reached 0.313 s into the crash event. The ridedown acceleration was 1.0 g's. The peak force (300 Hz data) for the impact event was 19.6 g's (36.3 kips (161 kN)). Because the sign/vehicle contact was brief the vehicle change in velocity was equal to the occupant impact velocity of 8.4 ft/s (2.6 m/s).

Photographs during the impact event are presented in figure 13. A

summary of the impact conditions and the test results is presented in figure 14. Figures 15 through 18 are data plots of data collected during the test. Pre- and post-test photographs of the vehicle and sign support system are shown in figures 19 through 22. Figure 23 depicts the measured vehicle crush for test 92F025.

## 7. CONCLUSION

The test results indicate that the 2 lb/ft (2.98 kg/m) braced sign support system meets all of the applicable safety criteria for the low- and high-speed test in weak soil specified by the FHWA. There was no occupant compartment intrusion during either test and the occupant impact velocities of 11.5 ft/s (3.5 m/s) for the low-speed test and 8.4 ft/s (2.6 m/s) for the high-speed test are below the 16 ft/s (4.9 m/s) limit specified by the FHWA. The stub remaining after each test was higher than the 4-in (101.6-mm) limit specified by the FHWA. However the flattening of the u-channel imparted no damage to the vehicle's undercarriage. The primary concern posed by the long stub was the pitch induced into the vehicle as it passed over the stubs during the low-speed test. It was believed that this would cause vaulting or rolling during high-speed impacts. The 60-mi/h (26.8-m/s) test demonstrated that the long stubs were not significant enough to cause vaulting or rolling, therefore the stubs were not a factor in considering compliance with the FHWA specifications.






Figure 1. Sketch of small sign support.

- NOTES:
1. ALL BOLTS & NUTS TO BE ALUMINUM.
  2. ALL U CHANNEL TO BE 2 LB/FT.
  3. U CHANNEL WIND BRACES MAY BE OTHER ALLOY.
  3. U CHANNEL UPRIGHTS AND STUBS TO BE 60 KSI STEEL.



3/8 DIA. 2PL

STEEL BRACKET DETAIL



- 5/16 GALV NUT
- 1.25 OD X 3/8 ID WASHER
- 2 LB/FT U CHANNEL, 60 KSI
- 5/16 X 2.5 GALV BOLT
- 1.25 OD X 3/8 ID WASHER
- 0.125 ALUMINUM BLANK

TEST SERIES 14

2 LB/FT U CHANNEL WITH BRACES		DATE: 11-1-68	BY: J. L. HARRIS
3 POSTS, 3 BIT		APPROVED BY:	DESIGNED BY:
ADLAN ENGINEERING COMP.		DATE: 11-1-68	BY: J. L. HARRIS
SS-014		ADLAN ENGINEERING COMP.	

1 in = 25.4 mm

Figure 2. Sketch of small sign support, attachment detail.



0.028 s




0.038 s



0.074 s



0.100 s



0.224 s



0.380 s

Figure 3. Test photographs during impact, test 92F024.



TEST NO. 92F024





Figure 5. Acceleration versus time, X-axis, test 92F024.


TEST NO. 92F024



1 ft = 0.305 m

Figure 6. Velocity versus time, X-axis, test 92F024.


# TEST NO. 92F024



1 lbf = 4.45 N    1 ft = 0.305 m

Figure 7. Force versus displacement, X-axis, test 92F024.

# TEST NO. 92F024



1 ft = 0.305 m

Figure 8. Occupant velocity and relative displacement versus time, X-axis, test 92F024.




Figure 9. Pretest photographs of test 92F024.




Figure 9. Pretest photographs of test 92F024 (continued).




Figure 10. Post-test photographs of test 92F024.




Figure 10. Post-test photographs of test 92F024 (continued).




0.010 s



0.022 s



0.038 s



0.070 s



0.124 s



0.294 s

Figure 11. Test photographs during impact, test 92F025.



# TEST NO. 92F025





Figure 13. Acceleration versus time, X-axis, test 92F025.


TEST NO. 92F025



1 ft = 0.305 m

Figure 14. Velocity versus time, X-axis, test 92F025.


# TEST NO. 92F025



1 lbf = 4.45 N    1 ft = 0.305 m

Figure 15. Force versus displacement, X-axis, test 92F025.

TEST NO. 92F025



1 ft = 0.305 m

Figure 16. Occupant velocity and relative displacement versus time, test 92F025.




Figure 17. Pretest photographs of test 92F025.




Figure 17. Pretest photographs of test 92F025 (continued).




Figure 18. Post-test photographs of test 92F025.





Figure 18. Post-test photographs of test 92F025 (continued).



8.0" 1.0" 1.0" 1.0" 1.0" 9.0"

Max Crush = 9 in

----- Post test

1 in = 25.4 mm

Figure 19. Sketch of vehicle crush, test 92F025.

## 8. REFERENCES

- (1) Jarvis D. Michie, *Recommended Procedures for the Safety Performance Evaluation of Highway Appurtenances*, National Cooperative Highway Research Program Report Number 230, March 1981.