

**CONCRETE BRIDGE DECKS
WITH ISOTROPIC REINFORCING**

SHORT TERM EVALUATION

**Final Report
OR-EF-99-06**

by

Eric W. Brooks, E.I.T.
Research Specialist

for

Oregon Department of Transportation
Research Unit
200 Hawthorne SE, Suite B240
Salem OR 97310

and

Federal Highway Administration
Washington DC 20590

September 1998

SI* (MODERN METRIC) CONVERSION FACTORS

APPROXIMATE CONVERSIONS TO SI UNITS

APPROXIMATE CONVERSIONS FROM SI UNITS

Symbol	When You Know	Multiply By	To Find	Symbol	When You Know	Multiply By	To Find	Symbol					
LENGTH													
in	inches	25.4	millimeters	mm	millimeters	0.039	inches	in					
ft	feet	0.305	meters	m	meters	3.28	feet	ft					
yd	yards	0.914	meters	m	meters	1.09	yards	yd					
mi	miles	1.61	kilometers	km	kilometers	0.621	miles	mi					
AREA													
in ²	square inches	645.2	millimeters squared	mm ²	millimeters squared	0.0016	square inches	in ²					
ft ²	square feet	0.093	meters squared	m ²	meters squared	10.764	square feet	ft ²					
yd ²	square yards	0.836	meters squared	m ²	hectares	2.47	acres	ac					
ac	acres	0.405	hectares	ha	kilometers squared	0.386	square miles	mi ²					
mi ²	square miles	2.59	kilometers squared	km ²	VOLUME								
fl oz	fluid ounces	29.57	milliliters	mL	milliliters	0.034	fluid ounces	fl oz					
gal	gallons	3.785	liters	L	liters	0.264	gallons	gal					
ft ³	cubic feet	0.028	meters cubed	m ³	meters cubed	35.315	cubic feet	ft ³					
yd ³	cubic yards	0.765	meters cubed	m ³	MASS								
oz	ounces	28.35	grams	g	grams	0.035	ounces	oz					
lb	pounds	0.454	kilograms	kg	kilograms	2.205	pounds	lb					
T	short tons (2000 lb)	0.907	megagrams	Mg	megagrams	1.102	short tons (2000 lb)	T					
TEMPERATURE (exact)													
°F	Fahrenheit temperature	5(F-32)/9	Celsius temperature	°C	Celsius temperature	1.8 + 32	Fahrenheit	°F					

NOTE: Volumes greater than 1000 L shall be shown in m³.



* SI is the symbol for the International System of Measurement

ACKNOWLEDGEMENTS

The author would like to thank the following Oregon Department of Transportation (ODOT) personnel for their contributions and help in gathering information for this report: Jeff Swanstrom, Gary Femling, Ron Clay, Larry Bush, Guido Portier, Michael Keifer and Anita Walker.

DISCLAIMER

This document is disseminated under the sponsorship of the Oregon Department of Transportation and the United States Department of Transportation in the interest of information exchange. The State of Oregon and the United States Government assume no liability of its contents or use thereof.

The contents of this report reflect the views of the author(s), who are responsible for the facts and accuracy of the data presented herein. The contents do not necessarily reflect the official policies of the Oregon Department of Transportation or the United States Department of Transportation.

The State of Oregon and the United States Government do not endorse products of manufacturers. Trademarks or manufacturers' names appear herein only because they are considered essential to the object of this document.

This report does not constitute a standard, specification, or regulation.

CONCRETE BRIDGE DECK WITH ISOTROPIC REINFORCEMENT

TABLE OF CONTENTS

1.0	INTRODUCTION	1
2.0	PROJECT DESCRIPTION.....	3
2.1	PROJECT LOCATIONS AND ENVIRONMENTS.....	3
3.0	POST-CONSTRUCTION DECK INSPECTIONS.....	5
3.1	USBR BRIDGE INSPECTIONS.....	5
3.2	CATCHING SLOUGH BRIDGE INSPECTIONS	9
3.3	SANTIAM OVERFLOW NO. 4	13
4.0	CONCLUSIONS.....	15
5.0	REFERENCES	17

APPENDICES

Appendix A: Crack Maps	19
Appendix B: Region Bridge Inspectors' Reports.....	30

LIST OF TABLES

Table 3.1: Depth of Concrete Cover for Top of Deck	9
--	---

LIST OF PHOTOS/FIGURES

Figure 2.1: Project locations in Oregon.	3
Figure 3.1: Cracks parallel to bents (April 1993)	5
Figure 3.2: Seismic activity in the Klamath Falls area (September 1993 – October 1994)	6
Figure 3.3: Transverse cracking was not visible (October 1993).....	7
Figure 3.4: Sealed cracks in October 1995 distorted cracking severity.....	7
Figure 3.5: Typical transverse cracks (April 1998)	8
Figure 3.6: Small changes in transverse cracks parallel to bents (April 1998).....	8
Figure 3.7: Plan and profile of Catching Slough Bridge	11
Figure 3.8: Transverse cracks were found on the bottom of the deck near center of span.	12
Figure 3.9: Transverse cracking is not found under the deck	12

Figure 3.10: The deck of Santiam Overflow No. 4 was placed in April 1994 13
Figure 3.11: Cracking on the top of the deck..... 14
Figure 3.12: Cracks on the bottom of the deck were outlined by efflorescence stains..... 14

1.0 INTRODUCTION

In September of 1992, the Oregon Department of Transportation (ODOT) replaced a bridge deck using isotropic deck steel. Isotropic decks include uniform reinforcement both longitudinally and transversely along the bottom and top of the deck, thereby giving an isotropically reinforced bridge deck. A few years later, two replacement bridges were constructed with the same pattern. A report entitled "Concrete Bridge Deck with Isotropic Reinforcing" (*Bush, 1996*) documents the deck construction. This report documents the two-year performance of these three bridge decks.

Good, long-term performance has been demonstrated by other research (*Fu, 1991*) for decks without construction or other early life problems. After eight years of service, the decks identified in the study performed as well as those with conventional reinforcement layouts.

Isotropic bridge deck reinforcing is being used as a cost-saving alternative. Using less steel for the same or better performance should produce cost savings in material and faster steel installation time. Long-term savings may result from reduced deck cracking severity, and consequently, a reduction in deck deterioration.

2.0 PROJECT DESCRIPTION

2.1 PROJECT LOCATIONS AND ENVIRONMENTS

In this study, the three bridge decks included; 1) a deck replacement on the USBR Bridge, constructed in 1992; 2) the new Catching Slough Bridge, completed in 1995; and 3) Santiam Overflow No. 4, built in 1994 and opened to traffic in 1996. The locations are shown in Figure 2.1.

The USBR Bridge (BR #8345A) is located on US 97 (Hwy 4) at milepost 273.71, near Klamath Falls, Oregon. This area has cold, dry, snowy winters and warm, dry summers. The average annual rainfall is 344 mm (13.4 in). The Average Daily Traffic (ADT) is 6,100 with 30% trucks.

Catching Slough Bridge (BR #2278E) is located on the Coos River Highway (Hwy 241) at milepost 2.46, near Coos Bay, Oregon. This area has mild winters and summers with very few freezing periods. The average annual rainfall is 2.1 m (6 ft 10 in). The ADT is 4,100 with 25% trucks.

The Santiam Overflow No. 4 (BR # 17342), is located northbound on Interstate 5 (Hwy 1) at milepost 240.42 near Salem, Oregon. This area has mild winter and summers with some freeze-thaw periods. The average annual rainfall is 1.1 m (3ft 7in). The ADT is 48,000 with 15% trucks.




Figure 2.1: Project locations in Oregon.

3.0 POST-CONSTRUCTION DECK INSPECTIONS

All three bridges were inspected soon after construction. Detailed crack maps (see Appendix A) were not made until the spring of 1998. Thus, cracking due to traffic loads has not been established. Comments regarding the type of deck cracking are found in the bridge inspectors' reports in Appendix B. To some degree, all three decks did crack as described in the following sections.

3.1 USBR BRIDGE INSPECTIONS

An inspection of the deck was made before the bridge was completely opened to traffic. The deck was removed and replaced in staged construction. The southbound lanes were completed in October 1992 and carried all the traffic until the northbound lanes were completed in December 1992.

Some cracking near the bents was found and photographed, shown in Figure 3.1. Other cracking was also mentioned. However, a detailed crack map was not made, due to traffic on the southbound side and the contractor's equipment on the northbound side.



Figure 3.1: Cracks parallel to bents (April 1993).

Several earthquakes and aftershocks occurred in the Klamath Falls area between September 1993 and October 1994 (Figure 3.2). Scattered transverse cracks on the southbound side were difficult to find in October 1993 (Figure 3.3). By October 1994, after the seismic activity subsided, transverse cracking had spread, making it easier to spot. Many of these cracks were sealed with methacrylate in late summer 1995. In Figure 3.4, the cracking severity is distorted by the sealant. Because detailed crack maps were not made, a correlation between seismic activity and cracking cannot be made.

Figure 3.2: Seismic activity in the Klamath Falls area (September 1993 – October 1994)



Figure 3.3: Transverse cracking was not visible (October 1993).



Figure 3.4: Sealed cracks in October 1995 distorted cracking severity.

On April 14, 1998, a detailed survey of the deck was made. It included a crack map, photographs, and depth of cover for the reinforcing steel. Most of the cracks were difficult to find because the crack widths were very narrow. Cracks previously sealed with methacrylate were easier to spot. Some large cracks were found parallel to the bents. The bents on the USBR are at a skew angle of about sixty degrees (see crack map in Appendix A). Typical transverse cracking is shown in Figure 3.5, while cracking parallel to the bents is shown in Figure 3.6.



Figure 3.5: Typical transverse cracks (April 1998).



Figure 3.6: Small changes in transverse cracks parallel to bents (April 1998).

In addition to the crack map, the depth of cover for the rebar was checked with a rebar locator. Most of the rebar had the minimum recommended cover depth of 50.8 mm (2 in). The results can be seen in Table 3.1. Note that the northbound lanes had more cover and less cracking.

Table 3.1: Depth of Concrete Cover for Top of Deck

Southbound		Northbound	
Distance	Depth	Distance	Depth
0 m (0 ft)	58.42 mm (2.3 in)	3.66 m (12 ft)	58.42 mm (2.3 in)
3.66 m (12 ft)	55.88 mm (2.2 in)	8.54 m (28 ft)	68.58 mm (2.7 in)
7.32 m (24 ft)	53.34 mm (2.1 in)	13.42 m (44 ft)	71.12 mm (2.8 in)
7.95 m (26 ft)	68.58 mm (2.7 in)	17.08 m (56 ft)	83.82 mm (3.3 in)
17.08 m (56 ft)	68.58 mm (2.7 in)	21.96 m (72 ft)	81.28 mm (3.2 in)
20.74 m (68 ft)	50.40 mm (2.0 in)	25.62 m (84 ft)	71.12 mm (2.8 in)
24.40 m (80 ft)	38.1 mm (1.5 in)	30.5 m (100 ft)	71.12 mm (2.8 in)
28.06 m (92 ft)	53.34 mm (2.1 in)	34.16 m (112 ft)	81.28 mm (3.2 in)
34.16 m (112 ft)	60.96 mm (2.4 in)	39.04 m (128 ft)	81.28 mm (3.2 in)
37.82 m (124 ft)	53.34 mm (2.1 in)	42.70 m (140 ft)	91.44 mm (3.6 in)
41.48 m (136 ft)	43.18 mm (1.7 in)	47.58 m (156 ft)	106.68 mm (4.2 in)
45.14 m (148 ft)	66.04 mm (2.6 in)	51.24 m (168 ft)	126.54 mm (5.1 in)
53.38 m (175 ft)	58.42 mm (2.3 in)	57.95 m (190 ft)	96.52 mm (3.8 in)
57.04 m (187 ft)	68.58 mm (2.7 in)	61.61 m (202 ft)	91.44 mm (3.6 in)
61 m (200 ft)	68.58 mm (2.7 in)	65.27 m (214 ft)	88.90 mm (3.5 in)
62.83 m (206 ft)	68.58 mm (2.7 in)	68.93 m (226 ft)	66.04 mm (2.6 in)
66.49 m (218 ft)	53.34 mm (2.1 in)	72.59 m (238 ft)	68.58 mm (2.7 in)
73.20 m (240 ft)	50.4 mm (2.0 in)	76.25 m (250 ft)	68.58 mm (2.7 in)
76.86 m (252 ft)	73.66 mm (2.9 in)	79.91 m (262 ft)	73.66 mm (2.9 in)
82.96 m (272 ft)	66.04 mm (2.6 in)	82.96 m (272 ft)	81.28 mm (3.2 in)

3.2 CATCHING SLOUGH BRIDGE INSPECTIONS

Cracking on the top and the bottom of the deck was noticed soon after construction was complete in November 1994. The bridge opened to traffic in March 1995. The Region 3 Bridge Inspector noted “more than normal cracking...” on the 1996 inspection (see Appendix B). In March 1998, the Research Unit, with the help of the Region Bridge Inspector and the bridge designer, made a formal inspection of the deck. A crack map of the top of the deck was made, and photographs of the top and bottom of the deck were taken. A random check for depth of cover over the rebar was also done. The cover depth met the minimum required value of 50.8 mm (2 in).

Cracking on the surface was concentrated at the east end of the bridge. The columns on this end are shorter and, as noted by the bridge designer, Guido Portier, “...all the interior columns are fixed to the superstructure except for bent 4. When spans are restrained and no movement is allowed, the possibility of concrete deck shrinkage will increase. These shrinkage cracks occur when the deck is unable to shorten due to stiffness of the shorter columns. Longer columns are more flexible and allow more shortening of the deck.”

Figure 3.7 is a crack map superimposed on the top view of the deck along with a profile view. Note the tallest column at bent 4 is about 13.7 m (45 ft) above the pier. This section had the least cracking. See Appendix A for a detailed crack map. A majority of the cracks had very narrow widths and were difficult to see.

Longitudinal cracking was found on the west end in both the wheel paths and center of the lane. These cracks were narrow and difficult to see. More than normal longitudinal cracking was found near the end on span 3. Both the designer and the inspector recalled problems with equipment at this section during construction. Some of the deck concrete sat for a period of time before the contractor finished placing it. Working the concrete after a partial set can cause it to shrink-crack. Other surface distress included minor spalling and debris, such as wood chips and clamshells in the surface.

Although mapping cracks on the underside of the deck was not done because of the bridge height, photographs were taken. Most of the serious cracking was found near the east end on the bottoms of spans 8 through 11, as seen in Figure 3.8. Large transverse cracks with efflorescence were located near the diaphragms at center span. The taller columns near the west end did not have large visible cracks, as seen in Figure 3.9.



Figure 3.8: Transverse cracks were found on the bottom of the deck near center of span.



Figure 3.9: Transverse cracking is not found under the deck at the higher section of the structure.

3.3 SANTIAM OVERFLOW NO. 4

The deck of the Santiam Overflow No. 4 was completed in April 1994, and opened to traffic in the spring of 1996. Until the completion of the northbound construction, all Interstate 5 traffic was diverted to the twin, southbound structure over the main channel. Cracking on the top and especially the bottom was noticed soon after construction was complete. Although no formal crack maps were made, the Region Bridge Inspector commented there were "...transverse and longitudinal cracks underside of deck w/ light to moderate efflorescence throughout" (see Appendix B).




Figure 3.10: The deck of Santiam Overflow No. 4 was placed in April 1994. Note the isotropic layout of the rebar.

On February 26, 1998, the Research Unit, with the help of bridge designer Larry Bush and Region 2 Bridge Inspector Jeff Swanstrom, made a detailed inspection of the deck of Santiam Overflow No. 4. Both the top and bottom of the deck had transverse and longitudinal cracks, as shown in Figures 3.11 and 3.12. The bottom of the deck had large cracks, many even went through the deck. Stains on beams from water running through the cracks were found. A trench was also noted in the sand under the deck, apparently caused by water running from the surface through a large crack in the deck. Cracking on the underside of the deck was found over almost the entire surface with the frequency of cracking greater near the bents



Figure 3.11: Cracking on the top of the deck.



Figure 3.12: Cracks on the bottom of the deck were outlined by efflorescence stains.

4.0 CONCLUSIONS

The three bridges included in this study have all shown distress after construction. On Catching Slough Bridge and USBR Bridge, the cracking does not appear to be serious. However, the cracks found on the Santiam Overflow No. 4 go through the entire deck. Construction practices, not the use of the isotropic reinforcement steel pattern, probably caused the initial cracking. This is apparent from the random cracking found rather evenly spread over the entire top of deck of the Santiam Overflow No. 4.

On Catching Slough Bridge, equipment problems slowed the laydown procedure. Concrete strength and weather problems, discussed in "Concrete Bridge Deck with Isotropic Reinforcing USBR Canal Bridge in Klamath Falls" (*Bush, 1996*), and depth of cover problems found in the 1998 inspection, have caused much of the damage to the USBR Bridge. Poor construction practice of removing the form too soon is believed to have been a problem for the Santiam Overflow No. 4.

According to a study conducted by J.H. Allen (*Allen, 1991*) these types of cracks could develop into serious problems. The findings from that study indicate that once cracking starts on an isotropic deck, the reduced steel reinforcement is not strong enough to prevent further cracking. Thus, monitoring the three bridge decks should be continued on an annual basis. If crack growth slows or stops, the isotropic steel pattern would be as acceptable as the conventional truss bar system.

5.0 REFERENCES


Bush, Larry, "Concrete Bridge Deck With Isotropic Reinforcing USBR Canal Bridge in Klamath Falls", Oregon Department of Transportation (1996).

Fu, Alampalli, and Pezz. "Long-Term Serviceability of Isotropically Reinforced Bridge Deck Slabs" New York Department of Transportation (1991).


Allen, J.H. "Cracking, Serviceability, and Strength of Concrete Bridge Decks", Transportation Research Report No.1290 (1991).

APPENDIX A:
CRACK MAPS


Bottom of Deck
 as seen through top
 (X-ray)




Bottom of USBR Deck as seen April 1998 through the top.



Top view of Catching Slough deck, spans 1 through 3




Top view of Catching Slough deck, spans 4 through 7.




Top view of Catching Slough deck, spans 8 through 11.

Block 117



1/2" = 1' (5)



APPENDIX B:
REGION BRIDGE INSPECTORS' REPORTS

OREGON DEPARTMENT OF TRANSPORTATION
 Bridge Inspection Report

Page No: 1

Br No 08345

Br Name(6) USBR CANAL
 (7) US 97 (004)
 Rt(5b-e) 21000970
 WearSurf(108) 620
 AC Depth
 Temp.Struct(103)
 Insp Date(90) 02 01 97
 Insp Freq(91) 24
 Level of Imp
 ConfinedSpace
 District(2) 11
 Inspector 1 No. S0005
 Inspector 2 No. 000000
 C-Group R4 Monitor
 Signature *[Handwritten Signature]*
 H(122) 4
 Date(93B) NA
 MP(11) 273.71
 Len(49) 272
 Width(52) 62.6
 RType(5a) 1 on

CONDITION STATUS REPORT

NAT	ELE	ELEMENT	ENV	TOTAL QUANT	UNIT	% IN EA		File: Region4 PONTIS COND NBI						
						1	2	3	4	5	RAT			
BIS	MNT	DESCRIPTION												
58p	112	Concrete Deck-Bare	3	171	CSFt	100	0	0	0				8	
58s	102	Concrete-Bridge Railing	3	544	LnFt	100	0	0						
58s	092	Compression Joint Seal	3	140	LnFt	100	0	0						
	SF1	Concrete-Deck Cracking	3	1	Each	100	0	0	0					
	SF2	Concrete-Deck Soffit	3	1	Each	98	2	0	0	0				
59s	095	Elastomeric Bearing	1	30	Each	100	0	0						
59s	096	Move Bearing(Roller,Slider,Etc)	1	10	Each	100	0	0						
59p	007a	St-Exter-Open Girder-Paint A	1	136	LnFt	100	0	0	0	0			8	
59p	007b	St-Inter-Open Girder-Paint A	1	408	LnFt	100	0	0	0	0			8	
59p	010a	Ext-Concrete-Open Girder	1	408	LnFt	100	0	0	0				8	
59p	010b	Int-Concrete-Open Girder	1	1632	LnFt	100	0	0	0				8	
59p	035	Concrete-Floor Beam	1	210	LnFt	100	0	0	0				8	
59s	155	Steel-Diaphragm-Paint A	3	35	LnFt	100	0	0	0	0				
59s	159	Concrete-Diaphragm	1	14	LnFt	100	0	0	0					
60p	057	P/S Conc-Post,Col/PileExtn(Wet)	1	9	Each	100	0	0	0				8	
60p	051	Concrete-End Bent (Dry)	3	2	Each	80	20	0	0				8	
				70	LnFt									

OTHER NBI ITEMS

Traffic safety - ADEQUACY
 bridge railings ----- Item 36A : 1
 transitions ----- Item 36B : 1
 appr. guardrail ----- Item 36C : 1
 appr. guardrail ends ---- Item 36D : 1
 Channel & channel protect.- Item 61 : 8
 Operational Status----- Item 41 : A
 Bridge posting ----- Item 70 : 5
 Waterway adequacy ----- Item 71 : 8
 Approach alignment ----- Item 72 : 7

OTHER OBSERVED CONDITIONS

Deck Wearing Surface ----- : 8
 Deck Drains ----- : 8
 Approach Pavement & Embankmt : 8
 Approach Shoulder & Embankmt : 8
 Guardrail ----- : 8
 Debris on Cap/Bearing Area - : 7
 High Load Collisions ----- : 00

UNDER CONSTRUCTION

Contract Number :
 Widening ----- :
 Replacement --- :
 New ----- :

REMARKS

ELEM NO.	BENT/SPAN	MEMBER ID	C #	DEFICIENCY DESCRIPTION	TEMP REPAIR
112	S 1-4	deck	1	trans and other cracking in deck	
SF2	S 3,4	deck	1	minor shrinkage cracking	
007a	S 3	gird	1	stiffener damage to #1 girder	
007a	S 3	gird	2	crack in web/flng weld at stiff at mid span	

OREGON DEPARTMENT OF TRANSPORTATION
 Bridge Inspection Report

Page No: 2

Br No 08345

007b S 3 gird 1 rat hole, fab. burn hole, @mid sp on all, top and bottom
 007b S 3 gird 2 welds at bottom flange tapers not ground #5
 007b S 3 gird 3 girder sawed and repaired during 1993 redecking
 007b S 3 gird 4 crack in web/flng weld at top, at stiff , mid span
 051 B 1,5 joints 1 joint opening blocked by excess conc.

MAINTENANCE RECOMMENDATIONS

ELEM WORK NO.	ORDER	BENT/SPAN	MEMBER ID	C WORK # NEEDS LIST	EST COST	ACT COST	COMPLI DATE
112	BR CREW	S1-4	deck	1 seal with methacrylate, drip	001500	000000	000000
007b	BR CREW	S 3	gird	1 use die grind to smooth holes	000000	000000	030195
051	BR CREW	B1,5	joint	1 chip out excess conc under seal	001600	000000	000000

OREGON DEPARTMENT OF TRANSPORTATION

Bridge Inspection Report

Br No 02278E

Page No: 1

Br Name(6) CATCHING SLOUGH Insp Date(90) 02 96
 (7) HWY 241 COOS R HWY Rt(5b-e) 41000002 Insp Freq(91) 24 H(122) 241
 NearSurf(108) 101 Level of Imp D UW Cond Date(93B)1995 MP(11) 2.23
 AC Depth ConfinedSpace Inspector 1 No. S0011 Len(49) 1270
 Temp.Struct(103) District(2) 07 Inspector 2 No. Width(52) 42.7
 Signature Michael Kuffner C-Group Monitor RType(5a) 1 on

CONDITION STATUS REPORT

NAT	ELE	ELEMENT	ENV	TOTAL		% IN EA PONTIS COND NBI					
				QUANT	UNIT	1	2	3	4	5	RAT
58p	126	Concrete Deck-Prt w/Coated Bars	2	542	CSFt	100	0	0	0		8
58s	102	Concrete-Bridge Railing	2	2700	LnFt	100	0	0			
58s	105	Strip Seal	2	86	LnFt	100	0	0			
	SF1	Concrete-Deck Cracking	2	1	Each	100	0	0	0		
	SF2	Concrete-Deck Soffit	2	1	Each	60	40	0	0	0	
59s	143	Disk Bearing	2	10	Each	100	0	0			
59p	009a	Ext P/S Concret-Open Girder	2	2562	LnFt	100	0	0	0		8
59p	009b	Int P/S Concret-Open Girder	2	3843	LnFt	100	0	0	0		8
59p	035	Concrete-Floor Beam	2	400	LnFt	100	0	0	0		8
59s	159	Concrete-Diaphragm	2	352	LnFt	100	0	0	0		
60p	047	Conc-Posts, Col/Pile Extn(Dry)	2	20	Each	100	0	0	0		8
60p	051	Concrete-End Bent (Dry)	2	2	Each	100	0	0	0		8
				92	LnFt						
60p	065	Conc-SubmrgdSill, PileCap/Footng	2	7	Each	100	0	0	0		8
65s	100	Concrete-Approach Slab	2	2	Each	100	0	0	0		

OTHER NBI ITEMS

Traffic safety - ADEQUACY
 bridge railings ----- Item 36A : 1
 transitions ----- Item 36B : 1
 appr. guardrail ----- Item 36C : 1
 appr. guardrail ends ---- Item 36D : 1
 Channel & channel protect.- Item 61 : 9
 Operational Status----- Item 41 : A
 Bridge posting ----- Item 70 : 5
 Waterway adequacy ----- Item 71 : 9
 Approach alignment ----- Item 72 : 8

OTHER OBSERVED CONDITIONS

Deck Wearing Surface ----- : 7
 Deck Drains ----- : 8
 Approach Pavement & Embankmt : 8
 Approach Shoulder & Embankmt : 8
 Guardrail ----- : 8
 Debris on Cap/Bearing Area - : 8
 High Load Collisions ----- : 00

UNDER CONSTRUCTION

Contract Number :
 Widening ----- :
 Replacement --- :
 New ----- :

REMARKS

ELEM NO.	BENT/SPAN	MEMBER ID	C #	DEFICIENCY DESCRIPTION	TEMP REPAIR
126	ALL	DECK	1	THE RIDE IS ROUGH	
126	ALL	DECK	2	MORE THAN NORMAL CRK TOP & BTM	
126	ALL	DECK	3	TRANS. CRKS WITH EFFL. STAINS	
105	ALL	JOINT	1	JOINTS FULL OF DEBRIS ALREADY	

MAINTENANCE RECOMMENDATIONS

OREGON DEPARTMENT OF TRANSPORTATION
 Bridge Inspection Report

Page No: 2

Br No 17342

NO. ORDER SPAN ID # NEEDS LIST COST COST DATE

MEMO:
 NOTE: 15 MIN INSP (2 INSP.)
 DATA ENTRY 5 MIN.

* ** *** PAINT SYSTEM *** ** *

Type: Prime										
Steel Tons	Visual	Int.	Last Painted		Freq	Top	Contract No.			
Paint Cond	Env Quant Unit	1	2	3	4	5	Prev. Years Painted			

Comments

* ** *** LOAD RATING *** ** *

OperRating(64) 2 Type 84 Tons InvRating(66) 2 Type 50 Tons

L.R. Calc. Date			
Oper.Rating Factors	Posted Loads		
Type 3	Config	Tons	
3S-2	Config	Tons	
3-3	Config	Tons	

SPECIAL INSPECTIONS

OTHER INSPECTION ACTIVITIES

Frac Crit Insp	Date	NA	Freq	Cross Channel Prof	Date	Freq
Underwater Insp	Date	NA	Freq	Deck Survey	Date	Freq
Movable Insp	Date		Freq	Fatigue Prone	Date	Freq
Coastal Br Insp	Date		Freq	Snooper Insp	Date	Freq
Major Insp	Date		Freq	Timber Boring	Date	Freq
Segmental Insp	Date		Freq	Timber Boring(Rev)	Date	
Suspension Insp	Date		Freq	Clearance Measure	Date	
ElectroSlagWeld	Date		Freq	Quality Assurance	Date	
Redund Pin & Han	Date		Freq	Scour Monitor (113)	3 Date	

Next Scheduled Routine Inspection 4 17 1999
 Equipment Needed

CROSS-CHANNEL

Profile Date : 01 14 1997
 Initial Point:
 Or: TOP OF RAIL EAST SIDE.

Distance	Depth	Location	Distance	Depth	Location	Page Number: 01
50.5	13.0	BTM.RIPRAP				
73.6	16.6					
116.8	17.1	BTM.STRM.				
146.2	15.8	WATER ELEV.				

Page No: 3

OREGON DEPARTMENT OF TRANSPORTATION
Bridge Inspection Report

Br No 17342

146.2	21.8	SCOUR HOLE
136.0		EDGE OF SCOUR
158.2	19.8	" " "
175.2	16.0	BTM.RIPRAP
202.0		