

HE  
18.5 /  
.A34  
no.  
DOT-  
TSC-  
NHTSA-  
79-48

REPORT NOS. DOT-TSC-NHTSA-79-48

HS-805-029

//  
COMPARISON OF PRE AND POST ROAD TEST  
ULTRASONIC INSPECTION RESULTS ON  
134 PASSENGER TIRES

George Berube

U.S. DEPARTMENT OF TRANSPORTATION  
RESEARCH AND SPECIAL PROGRAMS ADMINISTRATION  
Transportation Systems Center  
3 Cambridge MA 02142



NOVEMBER 1979

FINAL REPORT

DEPARTMENT OF  
TRANSPORTATION

JAN 16 1980

LIBRARY

DOCUMENT IS AVAILABLE TO THE PUBLIC  
THROUGH THE NATIONAL TECHNICAL  
INFORMATION SERVICE, SPRINGFIELD,  
VIRGINIA 22161

Prepared for  
U.S. DEPARTMENT OF TRANSPORTATION  
NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION  
Office of Research and Development  
Washington DC 20590

NOTICE

This document is disseminated under the sponsorship of the Department of Transportation in the interest of information exchange. The United States Government assumes no liability for its contents or use thereof.

NOTICE

The United States Government does not endorse products or manufacturers. Trade or manufacturers' names appear herein solely because they are considered essential to the object of this report.

1. Report No. HS-805-029		2. Government Accession No.		3. Recipient's Catalog No.	
4. Title and Subtitle REPORT OF PRE AND POST ROAD TEST ULTRASONIC INSPECTION RESULTS ON 134 PASSENGER TIRES				5. Report Date November 1979	
				6. Performing Organization Code	
7. Author(s) George Berube				8. Performing Organization Report No. DOT-TSC-MHTSA-79-48	
9. Performing Organization Name and Address U.S. Department of Transportation Research and Special Programs Administration Transportation Systems Center Cambridge MA 02142				10. Work Unit No. (TRAIS) HS027/R0404	
				11. Contract or Grant No.	
12. Sponsoring Agency Name and Address U.S. Department of Transportation National Highway Traffic Safety Administration Office of Research and Development Washington DC 20590				13. Type of Report and Period Covered Final Report Jan. 1977-June 1979	
				14. Sponsoring Agency Code	
15. Supplementary Notes					
16. Abstract  A study was conducted to compare ultrasonic inspection data from 134 tires prior and subsequent to road tests in order to determine whether excessive tread wear could be related to characteristics detected by the ultrasonic inspection. Analysis of data on all tires after road test resulted in the finding that nine of the tires exhibited substantial changes which may be related to abnormal tread wear.					
17. Key Words Ultrasonic Non-Destructive Testing			18. Distribution Statement  DOCUMENT IS AVAILABLE TO THE PUBLIC THROUGH THE NATIONAL TECHNICAL INFORMATION SERVICE, SPRINGFIELD, VIRGINIA 22161		
19. Security Classif. (of this report) Unclassified		20. Security Classif. (of this page) Unclassified		21. No. of Pages 38	22. Price

HE  
18.5  
.A34  
AD,  
DOT-  
TSC-  
MHTSA  
79-48



## PREFACE

The work described herein was accomplished with the cooperation of W. J. Woehrle of UNIROYAL Inc., Detroit, Michigan and H. Meyer of Gummi-Meyer GMBH of Aachen, West Germany.


# METRIC CONVERSION FACTORS

## Approximate Conversions to Metric Measures

Symbol	What You Know	Multiply by	To Find	Symbol
		<b>LENGTH</b>		
in	inches	2.5	centimeters	cm
ft	feet	30	centimeters	cm
yd	yards	0.9	meters	m
mi	miles	1.6	kilometers	km
		<b>AREA</b>		
m <sup>2</sup>	square inches	6.5	square centimeters	cm <sup>2</sup>
ft <sup>2</sup>	square feet	0.09	square meters	m <sup>2</sup>
yd <sup>2</sup>	square yards	0.8	square meters	m <sup>2</sup>
mi <sup>2</sup>	square miles	2.6	square kilometers	km <sup>2</sup>
	acres	0.4	hectares	ha
		<b>MASS (weight)</b>		
oz	ounces	28	grams	g
lb	pounds	0.45	kilograms	kg
	short tons (2000 lb)	0.9	tonnes	t
		<b>VOLUME</b>		
teaspoon	teaspoons	5	milliliters	ml
fl oz	fluid ounces	16	milliliters	ml
c	cups	30	milliliters	ml
pt	pints	0.24	liters	l
qt	quarts	0.47	liters	l
gal	gallons	0.95	liters	l
ft <sup>3</sup>	cubic feet	3.8	cubic meters	m <sup>3</sup>
yd <sup>3</sup>	cubic yards	0.03	cubic meters	m <sup>3</sup>
		0.76	cubic meters	m <sup>3</sup>
		<b>TEMPERATURE (exact)</b>		
°F	Fahrenheit temperature	5/9 (then subtracting 32)	Celsius temperature	°C


## Approximate Conversions from Metric Measures

Symbol	What You Know	Multiply by	To Find	Symbol
		<b>LENGTH</b>		
mm	millimeters	0.04	inches	in
cm	centimeters	0.4	inches	in
m	meters	3.3	feet	ft
km	kilometers	1.1	yards	yd
		0.6	miles	mi
		<b>AREA</b>		
cm <sup>2</sup>	square centimeters	0.16	square inches	in <sup>2</sup>
m <sup>2</sup>	square meters	1.2	square yards	yd <sup>2</sup>
km <sup>2</sup>	square kilometers	0.4	square miles	mi <sup>2</sup>
ha	hectares (10,000 m <sup>2</sup> )	2.5	acres	ac
		<b>MASS (weight)</b>		
g	grams	0.036	ounces	oz
kg	kilograms	2.2	pounds	lb
t	tonnes (1000 kg)	1.1	short tons	
		<b>VOLUME</b>		
ml	milliliters	0.03	fluid ounces	fl oz
l	liters	2.1	pints	pt
l	liters	1.06	quarts	qt
m <sup>3</sup>	cubic meters	0.26	gallons	gal
m <sup>3</sup>	cubic meters	35	cubic feet	ft <sup>3</sup>
m <sup>3</sup>	cubic meters	1.3	cubic yards	yd <sup>3</sup>
		<b>TEMPERATURE (exact)</b>		
°C	Celsius temperature	9/5 (then add 32)	Fahrenheit temperature	°F



## TABLE OF CONTENTS

<u>Section</u>		<u>Page</u>
1.	INTRODUCTION AND SUMMARY.....	1
2.	DESCRIPTION OF EQUIPMENT.....	2
3.	PROCEDURE AND ANALYSIS OF NONDESTRUCTIVE INSPECTION DATA.....	6
4.	TIRE DESCRIPTION.....	17
5.	SUMMARY AND COMPARATIVE ANALYSIS.....	18
6.	ANNOTATED HARD COPY PRINTOUTS.....	20



## LIST OF ILLUSTRATIONS

<u>Figure</u>		<u>Page</u>
2-1	Ultrasonic Inspection System.....	3
2-2	Transducer Array.....	3
2-3	Transducer Locations.....	4
2-4	Ultrasonic Tire Scan Display.....	5
3-1	Scoring Form.....	7
3-2	High Quality Data Printout.....	8
3-3	Poor Quality Data Printout.....	9
3-4	Example of Poor Registration .....	10
3-5	Turn-up Area.....	11
3-6	Example of Inclusion.....	12
3-7	Example of Singularity/Shadow.....	13
3-8	Radial Runout.....	13
3-9	Lateral Runout.....	14
3-10	Intensity Change.....	14
3-11	Trace Discountinuity.....	15
3-12	Shape Discountinuity.....	16
6-1	Goodrich Custom Long-Miler---Radial Runout in Channel 10.....	21
6-2	Goodrich Custom Long-Miler---Apparent Treadware in Shoulder Area.....	22
6-3	Goodrich Custom Long-Miler---Some Tread Modulation..	23
6-4	Goodrich Custom Long-Miler---Heavy Splice in Channels 8 and 9 Causing Bulging Effect on Surface of Shoulder.....	24
6-5	Goodrich Custom Long-Miler---Bulging of Outer Surface Due to Belt Problem.....	25

LIST OF ILLUSTRATIONS (CONT'D)

<u>Figure</u>		<u>Page</u>
6-6	Uniroyal Tiger Paw Inclusions .....	26
6-7	Firestone #500---Definite Change in Shape in Channels 15 and 16.....	27
6-8	Goodyear Power Cushion 78---Severe Runout (Channels 9-15).....	28
6-9	Goodyear Poly Steel Radial---Channel 15 Indicates Some Shape Discontinuity .....	29

LIST OF TABLES

<u>Table</u>		<u>Page</u>
5-1	LIST OF DEGRADED TIRES WITH SCORES BEFORE AND AFTER ROAD TEST.....	19



## 1. INTRODUCTION AND SUMMARY

The principal objective of the study reported here was to compare data from 134 tires prior to and subsequent to road tests, in order to determine whether excessive tread wear could be related to characteristics detected by ultrasonic inspection.

The tires inspected by ultrasonics (described in Section 2), were road tested in accordance with a procedure described in Reference 1, were re-inspected ultrasonically and the two ultrasonic data sets were compared. The findings of this comparative analysis were that nine tires exhibited substantial changes in the ultrasonic data.

## 2. DESCRIPTION OF EQUIPMENT

Tire inspection by reflection ultrasound utilizes narrow band pulses of acoustic energy,<sup>(1)</sup> coupled to the tire by a water envelope.<sup>(2)</sup> The tire-handling part of the system used for this investigation is shown in Figure 2-1. It consists of a rotatable spider with three arms. On each arm, when in the vertical position out of the water, a tire can be mounted and inflated. The arm is then moved 120° into the inspection position where it is rotated through an array of transducers, shown in Figure 2-2 (shown out of the water for clarity). The inspection scan requires about 20 seconds after which the tire is returned to the vertical position deflated, removed, and replaced by another tire for inspection. Transducers are independently adjustable to ensure that the ultrasonic energy flux is perpendicular to the laminar structure of the tire. For a group of similar tires, the adjustment is carried out manually under water and requires about 30 minutes. No further adjustment is required for a sequence of similar tires from the same manufacturer. The location of transducers around a typical tire is shown in Figure 2-3. Figure 2-4 is a printout of the display produced by the inspection system. Along the horizontal axis of the display, there are twenty channels of information, one from each transducer. Channels designated 2 - 6 cover the serial number sidewall, channels 7 - 9, one shoulder, channels 10 - 13 the tread center, channels 14 - 16 the other shoulder, and channels 17 - 21 the other sidewall. The vertical axis of the display represents the 360° clockwise rotation of the tire when viewed from the serial-number side, with 0° at the top, 180° half-way down and 360° at the bottom.

---

(1) Feasibility of High Resolution Pulse-Echo Techniques for Automobile Tire Inspection, Ryan, R.P., June 1973, DOT-TSC-NHTSA-72-11, U.S. Department of Transportation, Interim Report.

(2) A Semi-Automated Pulse-Echo Ultrasonic System for Inspecting Tires, Ryan, R.P., July 1977, Interim Report, DOT-TSC-NHTSA-76-3 U.S. Department of Transportation .




FIGURE 2-1. ULTRASONIC INSPECTION SYSTEM




FIGURE 2-2. TRANSDUCER ARRAY




FIGURE 2-3. TRANSDUCER LOCATIONS




FIGURE 2-4. ULTRASONIC TIRE SCAN DISPLAY

### 3. PROCEDURE FOR ANALYSIS OF NONDESTRUCTIVE INSPECTION DATA

The analysis of the printouts was performed by individuals trained in data interpretation but having no knowledge of tire technology. A form (Figure 3-1) was then completed for each tire in the population. It lists the identification number, manufacturer, construction, ply material, and belt material. Across the top of the form, numbers 2 to 21 correspond to the 20 transducer channels on the printout. On the right side of the form are ten inspection criteria. Some of these criteria apply to individual channels, others apply to combinations of channels. A whole-number scoring value from 1 = poor to 9 = excellent is entered into the appropriate blocks by the evaluator. The inspection criteria and transducer channels to which they apply are defined below:

#### Data Quality (combination of all channels)

Degree of clarity and focus of traces, black and white detail and gray shades (good quality - Figure 3-2; poor quality, Figure 3-3).

#### Registration (combination of all channels)

The line-up accuracy of the 20 data channels. The complete printout consists of two pages placed side by side, channels 2 - 11 on the first page, channels 12 - 21 on the second page (Figure 3-4).

$\theta = 0^\circ$  location is different on the two traces, thereby preventing superposition for comparison purposes (poor registration).

#### Turnup Modulation (channels 2 and 21)

Abrupt brightness change (Figure 3-5). It is caused by overlapping or separation of material near the tire beads.

#### Inclusion (all channels)

A reflection from several depths and generally present in more than one channel (Figure 3-6), not be confused with a single trace separation or fading of a trace. It is caused by a hole or foreign material in the tire structure.






FIGURE 3-2. HIGH QUALITY DATA PRINTOUT




FIGURE 3-3. POOR QUALITY DATA PRINTOUT






FIGURE 3-4 . EXAMPLE OF POOR REGISTRATION



SEVERE TURNUP  
MODULATION



LITTLE OR NO  
TURNUP MODULATION

FIGURE 3-5. TURN-UP AREA



10

FIGURE 3-6. EXAMPLE OF INCLUSION

Singularity/Shadow (all channels)

A bright spot adjacent to a shadow (Figure 3-7). It is caused by a separation or other discontinuity.

Radial Runout (channel 10)

Skewed or wavy trace (Figure 3-8). Caused by "out of roundness": the resulting "high spot" passes closer to transducer #10 than the remainder of the tire scanned in Channel #10.

Lateral Runout (channels 5 and 18)

Wavy trace (Figure 3-9). Caused by a change in tire width.

Intensity Change

Abrupt brightness change (Figure 3-10). Caused by a change of material thickness.




FIGURE 5-7. EXAMPLE OF SINGULARITY/SHADOW





FIGURE 3-8. RADIAL RUNOUT



12

18

FIGURE 3-9. LATERAL RUNOUT




FIGURE 3-10. INTENSITY CHANGE


Trace Discontinuity (all channels)

Interruption of a trace (Figure 3-11); not to be confused with an inclusion which is usually indicated in more than one channel. It is caused by abnormal displacement of material.

Shape Discontinuity (all channels)

Abrupt change of shape of trace (Figure 3-12). It is caused by excess of material or distorted ply structure.

The scores for tread, belts, sidewall, and carcass are derived from the above inspection criteria, taking all factors known about the tire into account. An experienced tire inspector can readily be trained for this task.



17

FIGURE 3-11. TRACE DISCONTINUITY




FIGURE 3-12. SHAPE DISCONTINUITY

#### 4. TIRE DESCRIPTION

<u>Name</u>	<u>Quantity</u>	<u>Construction</u>	<u>Size</u>
Goodrich Custom Long Miler	21	2 Polyester and 2 Glass	H78-15
Uniroyal Tiger Paw	21	4 Ply Polyester	H78-15
Firestone Radial "500"	21	2 Polyester and 2 Steel	HR78-15
Cooper Lifeliner "78"	21	2 Polyester and 2 Glass	H78-15
Goodyear Power Cushion 78	21	4 Ply Polyester	H78-15
Goodyear Poly- steel Radial	29	2 Polyester and 2 Steel	HR78-15

## 5. SUMMARY OF COMPARATIVE ANALYSIS

The printouts from nondestructive inspection before and after road test were compared on a side by side basis. Of the 6 groups tested 9 tires revealed considerable degradations. Other tires in the groups showed some minor changes.

Five of the nine tires, (all Goodrich Custom Long Miler) developed Radial Runout or shape discontinuities in the sidewall. Shoulder variations were found in the remaining four tires. See Section 7 for a commentary describing degradations in each tire, along with possible cause.

The scores of the nine tires are given in Table 5-1.

Of the six groups investigated, 4 groups had only one tire which showed degradations; one group had five tires with degradations; one group had no degradation in any tire.

TABLE 5-1. LIST OF DEGRADED TIRES WITH SCORES BEFORE AND AFTER ROAD TEST

Name	Serial Number	SCORES								
		Before			After					
		T	B	S	C*	T	B	S	C	
Goodrich Custom Long Miler (Glass Belts)	T8X21119	9	8	7	8	7	6	7	7	
	T8X21222	7	8	6	7	7	7	6	7	
	T8X21233	7	7	7	7	7	7	7	**	
	T8X21244	8	8	7	8	6	7	7	**	
	T8X21255	9	7	7	7	9	7	7	**	
Uniroyal Tiger Paw (4-Ply)	T7X2199	9	NA	6	7	6	NA	6	7	
Firestone Radial "500" (Steel Belts)	T7X2236	8	7	7	8	6	7	7	8	
Goodyear Power Cushion 78 (4-ply)	T8X2270	7	NA	6	5	7	NA	5	5	
Goodyear Poly Steel Radial	T8X2302	9	9	8	8	7	8	7	7	


\* T - Tread  
 B - Belts  
 S - Sidewalls  
 C - Carcass

\*\* For degradation, see Figures 7-3 and 7-5.


## 6. ANNOTATED HARD COPY PRINTOUTS

Figures 6-1 through 6-9 are copies of the primary hardcopy ultrasonic data. The upper image was obtained before the road test and the lower after road test. The titles explain conditions observed in the tires.

T8X  
2119



BEFORE ROAD TEST




AFTER ROAD TEST

FIGURE 6-1. GOODRICH CUSTOM LONG-MILER ——— RADIAL RUNOUT IN CHANNEL 10. IT DID NOT APPEAR BEFORE ROAD TEST. POSSIBLE SEPARATION ? CHANNEL 19 ALSO HAS SOME SHAPE DISCONTINUITIES, BULGING OF OUTER SURFACE. DOES NOT APPEAR IN NEIGHBORING CHANNELS. POSSIBILITY OF EXCESS RUBBER.


T8X  
2122

9 10 11



BEFORE ROAD TEST

9 10 11




AFTER ROAD TEST

FIGURE 6-2. GOODRICH CUSTOM LONG-MILER --- APPARENT TREADWEAR IN SHOULDER AREA. DARK LINER TRACES IN CHANNEL 9 ARE SUSPICIOUS. PELTS SPERM TO HAVE SHIFTED SLIGHTLY IN CHANNELS 9, 10, and 11.

T8 X  
21 23

BEFORE ROAD TEST



AFTER ROAD TEST





FIGURE 6-3. GOODRICH CUSTOM LONG-MILER --- SOME TREAD MODULATION; MAY OR MAY NOT BE SPURIOUS. BELTS ARE NOT EVEN, SOME LATERAL RUNOUT INDICATED.


TSX  
2124

8 9



BEFORE ROAD TEST

8 9




AFTER ROAD TEST

FIGURE 6-4. GOODRICH CUSTOM LONG-MILER --- HEAVY SPLICE IN CHANNELS 8&9 CAUSING BULGING EFFECT ON SURFACE OF SHOULDER. THIS CAUSES OUT-OF-POUNDNESS AND IRREGULAR WEAR. SPLICE APPEARS TO BE MORE SEPARATED AFTER ROAD TEST.


T8X  
2125

15



BEFORE ROAD TEST

15




AFTER ROAD TEST

FIGURE 6-5. GOODRICH CUSTOM LONG-MILER — BULGING OF OUTER SURFACE DUE TO BELT PROBLEM. BELTS IN CHANNEL 15 SEEM TO HAVE DISCONTINUITIES. WOULD SUSPECT A POSSIBLE SEPARATION TO BE PRESENT. UNEVEN BELT SPLICES ARE KNOWN TO CAUSE UNEVEN TREADWEAR.


TSX  
2199

14 15 16



BEFORE ROAD TEST


14 15 16



AFTER ROAD TEST

FIGURE 6-6. UNIROYAL TIGER PAW INCLUSIONS OBSERVED IN CHANNELS 14 AND 16 BEFORE ROAD TEST ARE OBSERVED IN CHANNELS 15 AND 16 AFTER ROAD TESTS.

15 16



BEFORE ROAD TEST

T8X  
2236

15 16




AFTER ROAD TEST

FIGURE 6-7. FIRESTONE #500 — DEFINITE CHANGE IN SHAPE IN CHANNELS 15 AND 16. NOTICEABLE TREADWEAR. CAUSE DOES NOT SEEM TO BE ASSOCIATED WITH BELTS OR INNER SURFACE.


T8X  
2270

9 10 11 12 13 14 15



BEFORE ROAD TEST

9 10 11 12 13 14 15




AFTER ROAD TEST

FIGURE 6-8. GOODYEAR POWER CUSHION 78 — SEVERE RUNOUT (CHANNELS 9-15). CAUSES CIRCUMFERENTIAL OUT-OF-ROUNDNESS WHICH LEADS TO UNEVEN TREADWEAR.


T8X  
2302

BEFORE ROAD TEST

15



15



AFTER ROAD TEST

FIGURE 6-9. GOODYEAR POLY STEEL RADIAL CHANNEL 15 INDICATES SOME SHAPE DISCONTINUITY AFTER THE ROAD TEST. THIS WAS PROBABLY CAUSED BY A WEAK BOND BETWEEN TREAD AND CARCASS WHICH RESULTS IN HIGH SPOTS ON THE SURFACE.

HE 18.5 .A34  
NHTSA-79  
Berube, Geor

Comparison c  
road test l  
inspection

Form DOT F 172  
FORMERLY FORM DI





00347518

**U.S. DEPARTMENT OF TRANSPORTATION  
RESEARCH AND SPECIAL PROGRAMS ADMINISTRATION**

**TRANSPORTATION SYSTEMS CENTER  
KENDALL SQUARE, CAMBRIDGE, MA 02142**

**OFFICIAL BUSINESS  
PENALTY FOR PRIVATE USE, \$300**

POSTAGE AND FEES PAID

U.S. DEPARTMENT OF TRANSPORTATION  
613

