

Appendix 13

MAINTENANCE / REPAIR LOG

Wire Cable Median Barrier Systems

ACCIDENT #6 INFORMATION					
DATE:	<u>7/12/2005</u>	LIGHT CONDITION:	<u>NIGHT</u>		
TIME:	<u>UNKNOWN</u>	ROAD CONDITION:	<u>DRY</u>		
HIGHWAY:	<u>IH 20</u>	APPROX. REFERENCE MARKER:	<u>MM 419</u>		
DIRECTION OF TRAVEL:	EAST	WEST			
VEHICLE TYPE:	CAR	TRUCK	SEMI	UNKNOWN	
PROPERTY DAMAGE ONLY:	YES	NO	NUMBER OF INJURIES:	<u>N/A</u>	
(No Injuries/Fatalities)			NUMBER OF FATALITIES:	<u>N/A</u>	
PREVENT CROSSOVER:	YES	NO			
BRIEF DESCRIPTION OF INCIDENT:					
DPS CALLED IN DAMAGED TO WIRE ROPE BARRIER. VEHICILE WAS EVADING ARREST.					
REFER TO # 7, 9 & 10 PIC'S					

REPAIR INFORMATION					
DATE:	<u>7/12/2005</u>				
TIME:	<u>8:30 AM</u>				
PRODUCT:	BRIFEN	TRINITY	# OF EMPLOYEES:	<u>2</u>	
			# OF HOURS:	<u>6</u>	
# OF POSTS REPLACED:	<u>27</u>		MATERIAL COST:	<u> </u>	
			LABOR COST:	<u> </u>	
ENDTREATMENT INVOLVED:	YES	NO			