

Figure 11. Profile and rut depth measurements




Figure 12. Transverse **profilograph** device




Figure 13. Project sites location map




Figure 14. Transverse profile of Project 1




Figure 15. Transverse profile of Project 2




Figure 16. Transverse profile of Project 3




Figure 17. Transverse profile of Project 4




Figure 18. Transverse profile of Project 5




Figure 19. Transverse profile of Project 6




Figure 20. Transverse profile of Project 7




Figure 21. Transverse profile of Project 8




Figure 22. Transverse profile of Project 9




Figure 23. Transverse profile of Project 10




Figure 24. Transverse profile of Project 11




Figure 25. Transverse profile of Project 12




Figure 26. Transverse profile of Project 13




Figure 27. Transverse profile of Project 14




Figure 28. Transverse profile of Project 15




Figure 29. Transverse profile of Project 16




Figure 30. Transverse profile of Project 17




Figure 31. Transverse profile of Project 18




Figure 32. Transverse profile of Project 19




Figure 33. Transverse profile of Project 20




Figure 34. Transverse profile of Project 22




Figure 35. Transverse profile of Project 23




Figure 36. Transverse profile of Project 24




Figure 37. Transverse profile of Project 25




Figure 38. Transverse profile of Project 26




Figure 39. Transverse profile of Project 27




Figure 40. Transverse profile of Project 28




Figure 41. Transverse profile of Project 29




Figure 42. Transverse profile of Project 30




Figure 43. Transverse profile of Project 31




Figure 44. Transverse profile of Project 32




Figure 45. Transverse profile of Project 33




Figure 46. Transverse profile of Project 34




Figure 47. Transverse profile of Project 35




Figure 48 Typical view of C7-C coring



Figure 49 Project 80 (W.B)




Figure 50 Project 2 Pittsburgh Parkway (W.B)



Figure 5 Project 3 Pittsburgh Parkway E.B



Figure 52 Project 4 Pittsburgh Parkway (W.B)




Figure 53. Project 5, Route 30 (E.B.)




Figure 54 Project 5 Route 30 (E.B Closeup of ID-3 texture



Figure 55 Project 6 Route 30 (W.B




Figure 56 Project 70 E.B



Figure 57. Project 9, Pennsylvania Turnpike (Bedford County)



Figure 58. Project 90 (W.B. near N.Y. bord



Figure 59. Project 12, 1-81 (N.B.), Luzerne County