APPENDIX A6

HIGH CYCLE FATIGUE



Figure A6.1: 3IT12 Load and crack motion sensor ranges



Figure A6.2: 3IT12 North strain gage ranges



Figure A6.3: 3IT12 South strain gage ranges



Figure A6.4: 3T12 Load and crack motion sensor ranges



Figure A6.5: 3T12 North strain gage ranges



Figure A6.6: 3T12 South strain gage ranges



Figure A6.7: 5IT12-B1 Load and crack motion sensor ranges



Figure A6.8: 5IT12-B1 Load and crack motion sensor means



Figure A6.9: 5IT12-B1 North strain gage ranges



Figure A6.10: 5IT12-B1 South strain gage ranges



Figure A6.11: 3IT18 Load and crack motion sensor ranges



Figure A6.12: 3IT18 Load and crack motion sensor means



Figure A6.13: 3IT18 North strain gage ranges



Figure A6.14: 3IT18 North strain gage means



Figure A6.15: 3IT18 South strain gage ranges



Figure A6.16: 3IT18 South strain gage means



Figure A6.17: 6IT10 Load and crack motion sensor ranges



Figure A6.18: 6IT10 Load and crack motion sensor means



Figure A6.19: 6IT10 North strain gage ranges



Figure A6.20: 6IT10 North strain gage means



Figure A6.21: 6IT10 South strain gage ranges



Figure A6.22: 6IT10 South strain gage means



Figure A6.23: 6T10 Load and crack motion sensor ranges

Figure A6.24: 6T10 Load and crack motion sensor means



Figure A6.25: 6T10 North strain gage ranges



Figure A6.26: 6T10 North strain gage means



Figure A6.27: 6T10 South strain gage ranges



Figure A6.28: 6T10 South strain gage means



Figure A6.29: 8IT10 Load and crack motion sensor ranges



Figure A6.30: 8IT10 Load and crack motion sensor means



Figure A6.31: 8IT10 North strain gage ranges



Figure A6.32: 8IT10 North strain gage means



Figure A6.33: 8IT10 South strain gage ranges



Figure A6.34: 8IT10 South strain gage means



Figure A6.35: 9IT12-B1 Load and crack motion sensor ranges



Figure A6.36: 9IT12-B1 Load and crack motion sensor means



Figure A6.37: 9IT12-B1 North strain gage ranges



Figure A6.38: 9IT12-B1 North strain gage means



Figure A6.39: 9IT12-B1 South strain gage ranges



Figure A6.40: 9IT12-B1 South strain gage means



Figure A6.41: 9T12-B4 Load and crack motion sensor ranges



Figure A6.42: 9T12-B4 Load and crack motion sensor means



Figure A6.43: 9T12-B4 North strain gage ranges



Figure A6.44: 9T12-B4 North strain gage means



Figure A6.45: 9T12-B4 South strain gage ranges



Figure A6.46: 9T12-B4 South strain gage means