




FACING WEST



CLOSE-UP OF BRIDGE MOUNT



FACING EAST

Minnesota
Department of
Transportation

SRF
NO. 0942006



FIGURE 4
FREWAY SITE: INITIAL TEST
DEVICE LOCATIONS

FHWA Field Test of Monitoring of Urban Vehicle Operations
Using Non-Intrusive Technologies